


CEREX®
Spunbond Nylon



European Distributor:
anowo ltd.
www.anowo.com
Email: info@anowo.com

from Flake Handling System



1. PA6,6 resin (pellets) are conveyed to a resin dryer
2. PA6,6 resin is melted in an extruder and conveyed to a melt filter
3. Melt filter extracts contaminants and refines the PA6,6 for spinning
4. Melted PA6,6 is metered into specially formulated filtration packs with spinnerettes which configures the polymer into continuous filaments
5. Continuous filaments are blown down onto a laydown belt
6. Laydown belt conveys the sheet of continuous filaments to a chemically activating gas phase environment
7. Fabric is conveyed through a wash bath and squeeze rolls to remove any residual gas and then dried
8. Fabric is wound on a roll

For more information please contact us through info@anowo.com or call one of our customer service centers:

<p>anowo ltd., Basel, Schweiz Headquarters</p>	<p>anowo ltd., UK, represented by CELL UK</p>	<p>anowo ltd., Milano, Italien represented by CELL SRL</p>
<p>Neubadstrasse 7 Postfach CH-4015 Basel Switzerland Phone: +41 61 282 82 20 Fax: +41 61 282 82 29</p>	<p>CELL UK 19 westerham road sevenoaks TN13 2PX united kingdom Phone: + 44 1732 458 665 Fax: + 44 1732 450 335</p>	<p>CELL SRL viale andrea doria, 42 I-20124 milano (MI) italien tel: +39 02 91 98 34 28 fax: +39 02 91 98 34 21</p>